

Revisions to this document are noted by a stripe in the left-hand margin

#0919, Rev. A
July, 2019
Page 1 of 2

SUBJECT: Allison Transmission Service/Parts Information Release Notification

MODELS AFFECTED: ALL

Introduction:

This Service Tip is being issued quarterly to inform the Original Equipment Manufacturers (OEMs) and Service Channel of NEW and/or recently updated Major Service Publications and Parts Catalogs.

This letter updates all Major Service Publications and Parts Catalog releases that occurred during the previous quarter (April through June) of 2019.

Service Information:

The following Allison Transmission Major Service Publications Table has been updated to include releases made available during the 2nd Quarter of 2019:

Major Service Publications		
Product	Publication Type	Publication Number
3000	Service Manual (English)	SM4013EN_201902
3000	Service Manual (German)	SM4013DE_201705
4000	Service Manual (German)	SM4014DE_201706
4000	Service Manual (English)	SM4014EN_201904
3000/4000 (5th Gen)	Troubleshooting Manual (German)	TS7149DE_201610
H 40/50 EP™	Owner's Manual (English)	OM3491EN_201906
H 40/50 EP™	Service Manual (English)	SM4162EN_201905
H 40/50 EP™ Pre 4th Gen Controls	Troubleshooting Manual (English)	TS3715EN_201904
H 40/50 EP™	Troubleshooting Manual (English)	TS5812EN_201809
H 40/50 EP™	Troubleshooting Manual (English)	TS5812EN_201904

Parts Catalog:

The following Allison Transmission Parts Catalogs were updated and made available during the 2nd Quarter of 2019:

Parts Catalogs	
Product	Publication Number
1000/2000	PC3062EN_201901
3000	PC2150EN_201902
4000	PC2456EN_201902
5000/6000	PC1860EN_201901
5000 Vocational	PC7479EN_201901
6000 Vocational	PC7480EN_201901
8000 Series Off-Highway	PC1249EN_201903
8000 Off-Highway Vocational	PC7481EN_201903
9000 Series Off-Highway	PC1830EN_201903
9000 Off-Highway Vocational	PC7482EN_201903
H 40/50 EP™	PC3717EN_201904
TC10	PC7120EN_201901
Support Equipment	PC2809EN_201902